

CONTINENTAL MOTORS® AIRCRAFT ENGINE
SPECIAL SERVICE INSTRUCTION

CATEGORY 6
SSI17-09

Compliance Will Enhance Safety

TECHNICAL PORTIONS
FAA APPROVED

SUBJECT: Engine Oil Cooler (P/N 654585), Temporary Repair and Inspections Instructions

PURPOSE: To issue instructions for temporary repair and inspection of oil cooler.

COMPLIANCE: See document contents

MODELS

AFFECTED: Continental Motors (CMI) new or rebuilt IO-550-N and TSIO-550-K aviation gasoline (AvGas) engines.

SPECIAL SERVICE INSTRUCTIONS
ARE DISTRIBUTED DIRECTLY
TO THE AFFECTED ENGINE OWNERS
AS LISTED ABOVE AND ARE NOT PART OF THE
PUBLISHED
SERVICE DOCUMENT SET.
IF YOU ARE AN AFFECTED ENGINE OWNER OR
WANT FURTHER DETAILS, PLEASE CONTACT
CMI CUSTOMER SERVICE AT:
1-251-436-8299
1-888-826-5465.

ISSUED	REVISED		PAGE NO	DOC NO	REVISION
2017/12/22		P.O. Box 90 Mobile, AL 251-436-8299	1 of 2	SSI17-09	

Intentionally Left Blank

ISSUED	REVISED		PAGE NO	DOC NO	REVISION
2017/12/22		P.O. Box 90 Mobile, AL 251-436-8299	2 of 2	SSI17-09	