

SPECIAL SERVICE INSTRUCTION

SSI20-04A

Compliance Will Enhance Safety

TECHNICAL PORTIONS
FAA APPROVED

SUBJECT: Amplified Maintenance and Servicing Instructions for IO240B engines installed in DA20-C1 aircraft operated in training fleets

PURPOSE: Reduce valve varnish/carbon deposits from rich operation during extended ground operations and at high altitudes

COMPLIANCE: See Document Contents

MODELS

AFFECTED: IO240B

SPECIAL SERVICE INSTRUCTIONS

ARE DISTRIBUTED DIRECTLY

TO THE AFFECTED ENGINE OWNERS

AS LISTED ABOVE AND ARE NOT PART OF THE

PUBLISHED

SERVICE DOCUMENT SET.

IF YOU ARE AN AFFECTED ENGINE OWNER OR

WANT FURTHER DETAILS, PLEASE CONTACT

CONTINENTAL CUSTOMER SERVICE AT:

1-251-436-8299

1-888-826-5465.

Intentionally Left Blank

ISSUED
2020/06/09

REVISED
2020/12/14



DOC NO **REVISION**
SSI20-04 A

PAGE
2 of 2